



Photo 1 – View of the top of the airplane as it came to rest in a nose low position.



Photo 2 – View of the cockpit.



Photo 3 – The front of the airplane after being righted.



Photo 4 – Right side view of the airplane during recovery.