



**Photo 1 – Left side view of the wreckage taken shortly after the accident. (Photo courtesy of the Boger City Fire Department)**



**Photo 2 – View of the wreckage path from the initial impact point.**



**Photo 3 – View of right wing and fuselage.**



**Photo 4 – Front view of wreckage.**



**Photo 5 - The engine suspended for examination.**



**Photo 6 - Propeller (Photo courtesy of Lycoming)**