



Photo 1 – Forward view of airplane wreckage showing fuselage post-crash fire damage



Photo 2 – Left side view of wreckage



Photo 3 – Aft view of wreckage



Photo 4 – Right side view of wreckage



Photo 5 – View of cockpit and cabin section



Photo 6 – View of fire damaged left wing vented fuel cap and fuel port (top view)



Photo 7 – Bottom view of left side fuel port showing vent hole



Photo 8 – View of right wing showing tape over right fuel port filler



Photo 9 – Close up view of tape over right fuel port filler showing some heat damage



Photo 10 – View of right fuel port filler with tape peeled back for inspection, showing broken safety wire




Photo 11 – View of front of engine and propeller showing impact damage



Photo 12 – View of right side of engine showing impact damage




Photo 13 – View of left side engine showing impact and fire damage




Photo 14 – View of accessory section showing impact and fire damage