



Photo 1 – Photograph of the accident airplane at an unknown date and time prior to the accident flight (Photo Courtesy of KITPLANES).



Photo 2 - Overview of Internal Left Wing Structure



Photo 3 – View of the Left and Right Wing (Right Wing Above left wing)



Photo 4 – Fragment of Wing as Found at the Accident Site



Photo 5 – Main Wreckage at Jet Engine at the Accident Site