



Photo 1 – Main Wreckage Path (NTSB Photo)



Photo 2 – Tree Upended by Wreckage



Photo 3 – Cockpit Area (NTSB Photo)



Photo 4 – Cabin Door (NTSB Photo)



Photo 5 – Aft Fuselage Section (NTSB Photo)



Photo 6 – Empennage (NTSB Photo)



Photo 7 – Rudder (NTSB Photo)



Photo 8 – Engine (NTSB Photo)



Photo 9 – Engine (NTSB Photo)



Photo 10 – Propeller Assembly (NTSB Photo)



Photo 11 – Propeller Blade (NTSB Photo)



Photo 12 – Turbocharger Section (NTSB Photo)




Photo 13 – Spark Plugs (NTSB Photo)



Photo 14 – Cut Tree Limb (NTSB Photo)