



Photo 1 – Photograph Provided by MA State Aeronautics Department. Drone Photograph Depicting the Resting Position of the Airplane and the Approach End of Runway 16.



Photo 2 – FAA Digital Photograph. Rear View of the Inverted Airplane. Note the Displaced Right Main Landing Gear.