



Photo 1 – Left side view of airplane on taxiway with left main landing gear wheel separated (Courtesy of FAA)



Photo 2 – View of right side of airplane resting on nose section (Courtesy of the FAA)



Photo 3 – View of the left side of the fuselage over the left wing root displaying airframe buckling (Courtesy of the FAA)



Photo 4 – View of the aft of the airplane (Courtesy of the FAA)