



Photo 1 – Left Side View Photo of the Accident Gyroplane Taken Unknown Date.



Photo 2 – FAA Digital Photograph. View of the Gyroplane and Surrounding Area. Note the extensive Fire Damage.



Photo 3 – FAA Digital Photograph. View of the Separated main rotor blade piece under Cut tree, Located about 10 ft from Wreckage



Photo 4 – FAA Digital Photograph. View of the Heat Damaged Engine Assembly, Propeller Hub, 2 shattered Propeller Blades, and Section of Main Rotor Blade.



Photo 5 – FAA Digital Photograph. View of the Engine Assembly During Engine Examination.