




Photo 1 – Ground Scars and Airplane at the Accident Site

Photo courtesy of FAA



Photo 2 – View of Struck Hangars and the Airplane

Photo courtesy of FAA



Photo 3 – View of Airplane at Accident Site

Photo courtesy of FAA