



**Photo 1 – Damage to nose gear door. (Photo courtesy of the FAA)**



**Photo 2 – Damage to the belly of the airplane. (Photo courtesy of the FAA)**



**Photo 3 – Landing gear handle in the down position. (Photo courtesy of the FAA)**