




Photo 1 – Helicopter at the Accident Site and View of Rooftop Helipad (Photo Courtesy of FAA)



Photo 2 - Intake Valve from the No. 4 Cylinder (Photo Courtesy of FAA)