



Photo 1 – View of Cockpit and Cabin Area as Found (FAA)



Photo 2 – View of Cabin and Cabin Door as Found (FAA)



Photo 3 – View of Empennage and Tail Section as Found (FAA)