



Photo 1 – View of Helicopter as Found (FAA)



Photo 2 – View of Tailboom Deformation (FAA)



Photo 3 – View of Tailrotor Driveshaft Cover Damage (FAA)