



Photo 1 – Front View of Helicopter Damage



Photo 2 – Tail Boom Damage



Photo 3 – Tail Rotor and Boom Damage



Photo 4 – Ground Scars at Accident Location