



Photo 1 – Front View of Airplane Wreckage (Photo Courtesy of the FAA)



Photo 2 – Left Front View of Airplane Wreckage (Photo Courtesy of the FAA)



Photo 3 - Right Front View of Airplane Wreckage (Photo Courtesy of the FAA)



Photo 4 – Top of Engine Cowling (Photo Courtesy of the FAA)



Photo 5 - Empennage (Photo Courtesy of the FAA)



Photo 6 – Right Side View of Vertical Stabilizer and Rudder (Photo Courtesy of the FAA)