



Photo 1 – Accident Site – Courtesy of FAA



Photo 2 – Front View of Maine Wreckage – Courtesy of FAA



Photo 3 – Side View of Main Wreckage – Courtesy of FAA



Photo 4 – Main Impact Point – Courtesy of FAA



Photo 5 – Close Up of Main Impact Point – Courtesy of FAA



Photo 6 – Right Wing – Courtesy of FAA



Photo 7 – Propeller Blade – Courtesy of FAA



Photo 8 – Close Up of Propeller Blade – Courtesy of FAA



Photo 9 – Engine and Propeller – Courtesy of FAA



Photo 10 – Left Wing – Courtesy of FAA



Photo 11 – Hand Throttle and Ignition Switches



Photo 12 – Close Up of Ignition Switches



Photo 13 – Keel Tube



Photo 14 - Trimmer



Photo 15 – Foot Throttle Lever



Photo 16 – Recovered Left Wing Battens



Photo 17 – Recovered Right Wing Battens



Photo 18 – Right Main Landing Gear



Photo 19 – Left Main Landing Gear



Photo 20 – Nose Landing Gear