



Photo 1 –View of Airplane at rest (Courtesy of Police)



Photo 2 – View of airplane and struck trees. (Courtesy of Police)



Photo 3 – View of airplane at rest with broken tree limb underneath wing. (Courtesy of Police)



Photo 4 – View of propeller (Courtesy of Piper)



Photo 5 – View of airplane after recovery.