



**Photo 1 – View of ground scars leading to airplane. (Courtesy of FAA)**



**Photo 2 – View of front of airplane damage looking aft towards ground scars. (Courtesy of FAA)**



**Photo 3 – Left fuel tank and wing damage. (Courtesy of FAA)**



**Photo 4 – Photograph of fuel selector. (Courtesy of FAA)**



**Photo 5 – View of left side of cockpit showing throttles and fuel selector handle. (Courtesy of FAA)**