



Photo 1 –View of all recovered pieces of airplane (Courtesy of FAA)



Photo 2 – View of Fuselage and Wing Sections Recovered (Courtesy of FAA)



Photo 3 – View of empennage section and rudder (Courtesy of FAA)