



Photo 1 – FAA Digital Photograph. View of the Helicopter Wreckage at the Accident Site.



Photo 2 - FAA Digital Photograph. View of the Wreckage at the Accident Site. The Helicopter was Resting on Its Left Side. Note the Fire Damage to the Helicopter and Surrounding Area.



Photo 3 - FAA Digital Photograph. View of a Portion of the Tailboom and Separated tail Rotor Assembly.



Photo 4 - FAA Digital Photograph. View of the Engine Assembly and Portion of Both Main Rotor Blades. Note the extensive fire damage to the Engine.



Photo 5 - FAA Digital Photograph. View of the Crankshaft and Engine Crankcase Half During the Engine Examination.