



Photo 1 – View of Airplane as Found (FAA)



Photo 2 – View of Damage to Underside of Right Wing (FAA)



Photo 3 – View of Fuel Samples (FAA)



Photo 4 – View of Water/Fuel Drained from Fuel System (FAA)