



Photo 1 – Left side view of airplane as it rests on runway. (Courtesy of FAA)



Photo 2 – View of nose gear and surrounding damage. (Courtesy of FAA)



Photo 3 – Closeup view of nose gear and damage. (Courtesy of FAA)



Photo 4 – View of nose gear actuator. (Courtesy of FAA)