



**Photo 1 – Airplane at the Accident Site Location (Photo Courtesy of FAA)**



**Photo 2 - Substantially Damaged Left Wing and Fuselage (Photo Courtesy of FAA)**