



Photo 1 – View of the wreckage path. (Photo courtesy of the FAA)



Photo 2 – Wreckage being recovered from the lake. (Photo courtesy of the FAA)



Photo 3 – View of the wreckage after being recovered from the lake. (Photo courtesy of the FAA)