



Photo 1 – View of airplane after recovery from lake. (Courtesy of WJBF News)




Photo 2 – View of open engine crankcase. Note fractured crankshaft. (Courtesy of FAA)




Photo 3 – Horizontal view of engine crankcase and fractured crankshaft. (Courtesy of FAA)