



Photo 1 – View of right side of fuselage showing buckling of wing and cabin section



Photo 2 - View of left side of fuselage showing collapsed left main landing gear



Photo 3 - View of left side of empennage showing buckling



Photo 4 – View of horizontal and vertical stabilizer showing buckling