



Photo 1 – View of Initial Ground Scars on Runway 23 (FAA)



Photo 2 – View of Ground Scars in Infield Grass (FAA)



Photo 3 – View of Airplane as Found Facing Intended Landing Direction (FAA)