



Photo 1 – FAA Digital Photograph. Right Forward Quartering View of the Resting Position of the Airplane.



Photo 2 - FAA Digital Photograph. View Depicting the Damage to the Outer Section of the Right Wing.



Photo 3 - FAA Digital Photograph. View Depicting the Separated Upper and Lower Undamaged Torque Links of the Right Main Landing Gear