



Photo 1 – View of the right side of the airplane where it came to rest. (Photo courtesy of the FAA)



Photo 2 – View of the left side of the airplane where it came to rest. (Photo courtesy of the FAA)



Photo 3 – View of the damage to the No. 3 cylinder.




Photo 4 – View of the damage to the No. 3 piston.