



Photo 1 – Close up of front of airplane damage. (Courtesy of FAA)



Photo 2 – Fuselage damage. (Courtesy of FAA)



Photo 3 – Right front side of airplane propeller damage. (Courtesy of FAA)



Photo 4 – Right side of airplane showing wing leading edge and fuselage damage. (Courtesy of FAA)



Photo 5 – Close up of steel spring landing gear failure area. (Courtesy of FAA)