



Photo 1 – View of the left side of the wreckage. (Photo courtesy of the FAA)



Photo 2 – View of the front of the wreckage. (Photo courtesy of the FAA)



Photo 3 – View of the tail section of the helicopter. (Photo courtesy of the FAA)



Photo 4 – View of the main rotor and fuselage. (Photo courtesy of the FAA)



Photo 5 – View of the tail rotor. (Photo courtesy of the FAA)