



Photo 1 – Main wreckage, front view.



Photo 2 – main wreckage, right quartering tail view.



Photo 3 – main wreckage, left wing view.



Photo 4 – main wreckage, left landing gear view.



Photo 5 – left main landing gear broken downlock link.



Photo 6 - Runway marks from left main landing gear.