



Photo 1 – Photograph of wreckage and accident site. (Courtesy of FAA)



Photo 2 – Photograph of wreckage showing cockpit seat resting on its left side. (Courtesy of FAA)



Photo 3 – Photograph of runway looking northwest. Note large tree and wreckage in background. (Courtesy of FAA)



Photo 4 – Grass wrapped around landing gear. (Courtesy of FAA)



Photo 5 – Tree with broken branches on ground near accident site. (Courtesy of FAA)



Photo 6 – Landing gear wheel tracks in grass bordering runway looking southeast. Grass is the same type that was found wrapped around landing gear. (Courtesy of FAA)