



Weather Observations

Heidi Kemner
Air Safety Investigator
Eastern Region Aviation

July 11, 2018

METAR/SPECI from KMLT, Millinocket, Millinocket Municipal Airport (United States) .	
SA 11/07/2018 23:53->	METAR KMLT 112353Z AUTO 35003KT 10SM CLR 23/06 A3003 RMK AO2 SLP172 T02280061 10261 20228 53010=
SA 11/07/2018 22:53->	METAR KMLT 112253Z AUTO 31006KT 10SM CLR 24/05 A3001 RMK AO2 SLP165 T02440050=
SA 11/07/2018 21:53->	METAR KMLT 112153Z AUTO 29007KT 250V320 10SM CLR 25/05 A3000 RMK AO2 SLP163 T02500050=
SA 11/07/2018 20:53->	METAR KMLT 112053Z AUTO VRB04KT 10SM CLR 25/06 A3000 RMK AO2 SLP161 T02500061 55000=
SA 11/07/2018 19:53->	METAR KMLT 111953Z AUTO 29009G15KT 10SM CLR 25/06 A2999 RMK AO2 SLP159 T02500056=
SA 11/07/2018 18:53->	METAR KMLT 111853Z AUTO 31008KT 10SM CLR 25/05 A2999 RMK AO2 SLP160 T02500050=
SA 11/07/2018 17:53->	METAR KMLT 111753Z AUTO 29010G15KT 250V330 10SM CLR 24/05 A3000 RMK AO2 SLP161 T02440050 10250 20161 57014=
SA 11/07/2018 16:53->	METAR KMLT 111653Z AUTO 31005KT 10SM CLR 24/07 A3001 RMK AO2 SLP166 T02440067=
SA 11/07/2018 15:53->	METAR KMLT 111553Z AUTO 10SM CLR 23/08 A3003 RMK AO2 SLP171 T02330083 PWINO \$=
SA 11/07/2018 14:53->	METAR KMLT 111453Z AUTO 32005KT 10SM CLR 22/08 A3004 RMK AO2 SLP175 T02220078 52002 PWINO \$=
SA 11/07/2018 13:53->	METAR KMLT 111353Z AUTO 30004KT 10SM CLR 21/08 A3004 RMK AO2 SLP175 T02110078 PWINO \$=
SA 11/07/2018 12:53->	METAR KMLT 111253Z AUTO 32006KT 10SM CLR 19/08 A3004 RMK AO2 SLP174 T01890083=
SA 11/07/2018 11:53->	METAR KMLT 111153Z AUTO 32003KT 10SM FEW060 16/07 A3003 RMK AO2 SLP174 T01610072 10161 20122 51016=
SA 11/07/2018 10:53->	METAR KMLT 111053Z AUTO 00000KT 10SM CLR 16/07 A3003 RMK AO2 SLP173 T01560072=
SA 11/07/2018 09:53->	METAR KMLT 110953Z AUTO 00000KT 10SM CLR 13/07 A3001 RMK AO2 SLP168 T01330072=
SA 11/07/2018 08:53->	METAR KMLT 110853Z AUTO 35004KT 10SM CLR 15/06 A2999 RMK AO2 SLP157 T01500056 51010=
SA 11/07/2018 07:53->	METAR KMLT 110753Z AUTO VRB03KT 10SM SCT065 14/08 A2998 RMK AO2 SLP156 T01440078=