

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Haverhill State: NH
 ZIP: 03774 Country: USA
 Latitude: 44 04' 48.62N Longitude: 072 00' 22.94W
(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 07/29/2018 Local Time: 12:05 PM
mm/dd/yyyy
 Time Zone: Eastern

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N221EZ

Manufacturer: Old West Funding

Model: SeaRey

Serial Number: 1D403C

Year of Manufacture: 2006

Amateur-Built: ☒ Yes ☐ No If Yes: ☐ Kit/Plans ☐ Original Design Make: Progressive Aerodyne

☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 1430 lbs

Weight at Time of Accident/Incident: 1362 lbs

Number of Seats: 2 Flight Crew Seats: _____

Cabin Crew Seats: _____ Passenger Seats: _____

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☐ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate (Check all that apply)

Standard

- ☐ Normal
- ☐ Aerobatic
- ☐ Balloon
- ☐ Commuter
- ☐ Transport
- ☐ Utility

Special

- ☐ Restricted
- ☐ Limited
- ☐ Provisional
- ☐ Special Flight
- ☒ Experimental
- ☐ Special Light-Sport
- ☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☐ Tricycle
- ☒ Amphibian
- ☐ Emergency Float
- ☐ Float
- ☒ Hull
- ☐ Other Launch/Recovery System
- ☐ None
- ☒ Tailwheel
- ☐ High Skid
- ☐ Skid
- ☐ Ski
- ☐ Ski/Wheel
- ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating
- ☐ Turbo Shaft
- ☐ Turbo Prop
- ☐ Turbo Jet
- ☐ Turbo Fan
- ☐ Electric
- ☐ Liquid Rocket
- ☐ Solid Rocket
- ☐ Hybrid Rocket
- ☐ None
- ☐ Unknown

Fuel System Type (Reciprocating)

- ☒ Carburetor
- ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. <i>mm/dd/yyyy</i>	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Rotax	914ULS	4419451	2006	115	753.5	82.8	
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour
- ☐ AAIP
- ☐ Annual
- ☐ Continuous Airworthiness
- ☒ Conditional Inspection
- ☐ Unknown

Date Last Inspection: 08/14/2017

mm/dd/yyyy

Airframe Total Time: 753.5 hrs

hours measured at (Select one)

- ☐ Last Inspection
- ☐ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☐ Annual
- ☐ Conditional (Amateur-built only)
- ☐ Manufacturer's Inspection Program
- ☐ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
- ☐ Specify: _____

Propeller 1

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☒ Ground Adjustable

Manufacturer: Warp drive

Model: _____

Propeller 2

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: AmeriKing

Model or Part No.: _____

TSO No.: ☐ C91 (121.5 MHz) ☐ C91a (121.5 MHz)
☐ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☒ No

If activated:

Did ELT Aid in Locating Aircraft: ☐ Yes ☒ No

If not activated:

- Indicate Reason:
- ☐ Impact Damage
 - ☐ Fire Damage
 - ☐ Battery Expired/Damaged
 - ☒ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
- ☐ Airframe Parachute
- ☐ Angle of Attack Indicator
- ☐ Autopilot
- ☐ Data Recorder
- ☒ Electronic Flight Bag or Handheld Device
- ☐ Electronic Multifunction Display
- ☐ Electronic Primary Flight Display
- ☐ Handheld GPS
- ☐ Heads Up Display
- ☐ Onboard Weather
- ☐ Satellite Tracking Device
- ☐ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Charles LewisCity: GilfordFractional Ownership Aircraft: ☐ Yes ☒ NoState: NHZIP: 03249Country: USA**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____

ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437

☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial

☐ Public Aircraft (Select one)

- ☐ Armed Forces
☐ Federal
☐ State
☐ Local

☐ Unknown**Revenue Operation for FAR 121, 125, 129, 135**
(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International

☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)Airport Name: Near Dean Memorial AirportAirport Identifier: 5B9Proximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/ADistance From Airport Center: 1.6 smDirection From Airport: 270 degrees trueAirport Elevation: 582 ft. msl**Runway Information**

Runway ID: _____ (L/R/C) Length: _____ ft Width: _____ ft

Runway/Landing Surface (Check all that apply)

- ☐ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☐ Dry ☐ Snow-Compacted ☒ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☒ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Final ☐ Crosswind ☐ Aborted Landing (after touchdown)
☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR ☐ Visual
☐ VOR/DME ☐ Localizer Only ☐ Contact
☐ TACAN ☐ LOC-back course ☐ Circling
☐ RNAV ☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☒ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☒ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot ☐ Co-Pilot ☐ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Charles

Middle Initial: E

Last Name: Lewis

City of Residence: Gilford

State: NH

ZIP: 03249

Country: USA

Age at time of Accident/Incident: 61

Date of Birth:

mm/dd/yyyy

Certificate Number:

Degree of Injury

☐ None ☐ Fatal
☐ Minor ☐ Unknown
☒ Serious

Seat Occupied

☒ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☒ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☐ Pilot
☒ Other
☐ Unknown

Medical Certificate

☐ None ☒ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☒ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

12/20/2017
mm/dd/yyyy

Medical Certificate Limitations

Must wear corrective lenses

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

12/23/2017

mm/dd/yyyy

Flight Review Aircraft

Make: Progressive Aerodyne

Model: SeaRey

Airplane Rating(s) (Check all that apply)

☐ None
☒ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☒ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☒ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☒ None
☐ Airplane Single-Engine ☐ Instrument Airplane
☐ Airplane Multi-Engine ☐ Instrument Helicopter
☐ Gyroplane ☐ Helicopter
☐ Powered Lift ☐ Glider
☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)

	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	760	498	760		6					
Pilot in Command (PIC)	700	498	700							
Time as Instructor										
This Make/Model										
Last 90 Days	20.9	20.9	20.9							
Last 30 Days	13.5	13.5	13.5							
Last 24 Hours	0	0	0							

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury

☐ None
 ☐ Fatal
☐ Minor
 ☒ Unknown
☐ Serious

Seat Occupied

☐ Left
 ☐ Front
 ☐ Unknown
☐ Right
 ☐ Rear
☐ Center
 ☐ Single

Restraint Type

Available
☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown
Used
☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None
 ☐ Flight Instructor
 ☐ Commercial
 ☐ US Military
☐ Private
 ☐ Recreational
 ☐ Airline Transport
 ☐ Foreign
☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None
 ☐ Class 3
☐ Class 1
 ☐ Driver's License (Sport Pilot only)
☐ Class 2
 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers
 ☐ Unknown
☐ With limitations/waivers
 ☐ N/A
☐ Special Issuance

Date of Last Medical

mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

mm/dd/yyyy

Flight Review Aircraft

Make: _____
 Model: _____

Airplane Rating(s)

(Check all that apply)
☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)
☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)
☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)
☐ None
☐ Airplane Single-Engine
☐ Airplane Multi-Engine
☐ Gyroplane
☐ Powered Lift
☐ Instrument Airplane
☐ Instrument Helicopter
☐ Helicopter
☐ Glider
☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)

	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)

Crew Name and Address

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____

Seat Occupied

☐ Left ☐ Front
☐ Center ☐ Rear
☐ Right ☐ Single
☐ Unknown ☐ Unknown

Injury

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Restraint Type:

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Type Rating/Endorsement for Accident/Incident Aircraft?

☐ Yes ☐ No

Total Flight Time at the Time of this Accident/Incident: _____ hrs

Crew Name and Address

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____

Seat Occupied

☐ Left ☐ Front
☐ Center ☐ Rear
☐ Right ☐ Single
☐ Unknown ☐ Unknown

Injury

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Restraint Type:

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Type Rating/Endorsement for Accident/Incident Aircraft?

☐ Yes ☐ No

Total Flight Time at the Time of this Accident/Incident: _____ hrs

PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)

Name and Address

First Name: David City: Hampstead
 Middle Initial: W State: NH ZIP: _____
 Last Name: Faxon Country: USA

☐ Crew ☐ Passenger ☐ Other

Seat

☐ Left
☐ Center
☒ Right
☐ Unknown
 Row: _____

Injury

☐ None
☐ Minor
☒ Serious
☐ Fatal
☐ Unknown

Restraint Type

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☒ 3-point ☒ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Age

☐ Under 5 years
 If Under 5,
☐ Child Restraint
☐ Lap-Held
☐ Unknown

First Name: _____ City: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____

☐ Crew ☐ Passenger ☐ Other

☐ Left
☐ Center
☐ Right
☐ Unknown
 Row: _____

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

☐ Under 5 years
 If Under 5,
☐ Child Restraint
☐ Lap-Held
☐ Unknown

First Name: _____ City: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____

☐ Crew ☐ Passenger ☐ Other

☐ Left
☐ Center
☐ Right
☐ Unknown
 Row: _____

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

☐ Under 5 years
 If Under 5,
☐ Child Restraint
☐ Lap-Held
☐ Unknown

First Name: _____ City: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____

☐ Crew ☐ Passenger ☐ Other

☐ Left
☐ Center
☐ Right
☐ Unknown
 Row: _____

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

☐ Under 5 years
 If Under 5,
☐ Child Restraint
☐ Lap-Held
☐ Unknown

FLIGHT ITINERARY INFORMATION

Last Departure Point

Airport ID: KLCI
 City: Laconia
 State: NH
 Country: USA

Time of Departure

Time: 11:00AM
 Time Zone: Eastern

Destination

Airport ID: Connecticut River
 City: Haverhill
 State: NH
 Country: USA

Type Flight Plan Filed

☒ None ☐ VFR/IFR
☐ Company VFR ☐ IFR
☐ Military VFR ☐ Unknown
☐ VFR
 Activated? ☐ Yes ☐ No ☐ Unknown

Type of ATC Clearance/Service (Check all that apply)

☒ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise
☐ VFR ☐ IFR ☐ VFR On Top ☐ Traffic Advisory ☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☒ Class G ☐ Military Operations Area (MOA) ☐ Special
☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area
☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown
☐ Class D ☐ Prohibited Area ☐ TRSA
☐ Class E ☐ Restricted Area ☐ FAR 93

Altitude of In-Flight Occurrence: 570 ft msl

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☒ National Weather Service ☐ Company
☐ Flight Service Station ☐ Military
☐ TV/Radio ☒ Internet
☒ Automated Report ☐ None
☐ Commercial Weather Service (DUATS) ☐ Unknown
☐ On-Board Weather

Weather Observation Facility

Facility ID: KLCI
 Observation Time: 11:00AM
 Time Zone: Eastern
 Distance from Accident Site: 40 nm
 Direction from Accident Site: 150 degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☐ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☒ Scattered

Ceiling

☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Temperature: _____ (C) or 80 (F)

Dew Point: _____ (C) or 75 (F)

Altimeter Setting: 30.04290 in. Hg
 or _____ MB

Lowest Cloud Condition Height

4000 ft agl

Ceiling Height

_____ ft agl

Wind Direction

☐ Variable

-or-
 Direction: 290 degrees true

Wind Speed

☐ Calm
☐ Light and Variable

-or-
 Speed: 6 kts

Wind Gusts

☒ Not Gusting

-or-
 Speed: _____ kts

Visibility 10 miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: 1500 ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☐ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None ☐ Drizzle ☐ Freezing Rain
☐ Rain ☐ Ice Pellets ☐ Snow Shower
☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower
☐ Hail ☐ Snow Grains ☐ Freezing Drizzle
☐ Rain Showers ☐ Ice Crystals

Restriction to Visibility (Check all that apply)

☒ None ☐ Fog
☐ Blowing Dust ☐ Ground Fog
☐ Blowing Sand ☐ Haze
☐ Blowing Snow ☐ Ice Fog
☐ Blowing Spray ☐ Smoke
☐ Dust ☐ Unknown

Icing Forecast

Amount ☒ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Icing Actual

Amount ☒ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Turbulence

Type (Check all that apply)
☒ None ☐ Light
☐ Clear Air ☐ Moderate
☐ Terrain-Induced ☐ Severe
☐ Convective Turbulence ☐ Extreme

NOTAMS (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Carbon fiber hull and nose cone broke forward of cockpit due to water impact. Full extent of airframe damage unknown at this time.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

VFR weather at departure airport and enroute: Wind 290 @6 SCT 3500 Temp 80/ Dewpt 75. Alt 30.04 The SeaRey pleasure flight began with a VFR departure from Rwy 26 Laconia airport at approx. 11:00 local time. The flight was planned to land on the Connecticut River just west of Haverhill, NH Dean Mem. Airport, 40mi NW of Laconia. The flight progressed as planned, climbing enroute to 6500' over scattered clouds topping at 5000', then descending over the Connecticut river valley to a 1/2 mile straight section of river I had landed 10 times in the past 19 years of water operations. Two water landings were completed this day. The first landing was a touch and go, continuing airborne to the North to check for boat traffic. The second landing southbound transitioned to a step taxi and continued 1/2 mile down-river of the landing area to a full stop. I then took off northbound up-river for a planned 3rd and final landing, intending to beach at a sandy shore area to join a friend who had already landed and beached his SeaRey. After take-off and climbing clear of the riverbed, I turned East and started a left teardrop turn over a flat cornfield to return, planning a 45 degree left turn re-entry over the river at about 50'AGL. Upon crossing the East shoreline and initiating the left turn, the control stick would not move past the vertical position for no readily observable reason. With the tree-lined West shoreline ahead and unable to turn, I selected full throttle and straight ahead as the only available option. However, it soon became apparent that I did not have the power to climb clear of the trees ahead, and we impacted the left-upper crown of a 60 ft tree on the West bank. The aircraft fell clear of the tree in a nose-down, left wing low attitude to the water with no control. My passenger and I were able to unbuckle and swim clear of the SeaRey, but were separated by the current. Each of us eventually made it to the West shore. My passenger was airlifted to Lebanon and I was transported to the local Woodsville hospital.

RECOMMENDATION (How could this accident/incident have been prevented?)**Operator/Owner Safety Recommendation**

After the crash, I researched what could cause a SeaRey control stick to fail to move past the vertical position in flight. I learned from on-line owner's website that a foreign object in the cockpit could come loose and become lodged in the confined area under the seats where the control stick pivots in close proximity to the floor and longitudinal hull stringers. Upon posting my account of the incident on a private SeaRey owners-only website, I learned that this control jam issue has been previously reported by other owner / builders. The SeaRey community responded within 2 days of my request to address this issue of control jamming, with one member suggesting a design for an aluminum guard to protect the open stick-movement area from the entry of loose cockpit objects i.e. equipment, cameras, cell phones, water bottles, etc. to prevent any restricted movement of the control stick. Having felt the unusual restricted movement of the control stick to the left, I suspect this is the most likely cause of my inability to move the control stick to the left to complete a normal turn.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☐ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

See above description

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

16.5 gal _____ Gallons

Fuel Type

☐ 80/87

☐ 115/145

☐ Jet B

☐ Other, specify _____

☐ 100 Low Lead

☐ Jet A

☐ JP8

☐ 100/130

☐ Jet A-1

☒ Automotive

Other Services, if Any, Prior to Departure

EVACUATION OF AIRCRAFT

Was an emergency evacuation of the aircraft performed? ☐ Yes ☒ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

Both myself and my passenger were able to unbuckle seat belts and swim clear of the aircraft to end up separated by several hundred feet on the West shoreline.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed

☐ Minor

☐ Substantial

☐ None

Registered Owner of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

08/15/2018

mm/dd/yyyy

Name of Pilot/Operator: Charles Lewis

Signature: _____

-- or --

☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or --

☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

ERA19LA204

Reviewed by NTSB Regional Office

ERA

Name of Investigator

L. Read

Date Report Received

8/15/2018