



Photo 1 – Photograph of damage on accident airplane from striking stop sign.



Photo 2 – Photograph of involved stop sign on service drive.




Photo 3 – Aerial photograph of the taxiway and service drive.