



Photo 1 – Debris Path (Photo Courtesy Mount Pleasant Fire Department)



Photo 2 – Main Wreckage (Photo Courtesy Mount Pleasant Fire Department)



Photo 3 – Fuel Selector (Photo Courtesy Mount Pleasant Fire Department)



Photo 4 – Engine (Photo Courtesy of FAA)