



Photo 1 – View of main wreckage from left side (Courtesy of FAA)



Photo 2 – View of left wing showing crush damage (Courtesy of FAA)