



Photo 1 –Right profile view of airplane being removed by ground crew. (Courtesy of FAA)



Photo 2 –View of left leading edge wing damage. (Courtesy of FAA)



Photo 3 –Photograph of airplane, windshield, and fence damage. (Courtesy of FAA)