



Photo 1 – Airplane Wreckage at Accident Site (Photo taken by FAA)



Photo 2 – Picture of the Airplane's V-Tail (Photo taken by FAA)