



Photo 1 – Main wreckage, front inverted view. (FAA)



Photo 2 - #4-cylinder, fractured exhaust valve




Photo 3 - #4-cylinder, piston.