



Photo 1 – Airplane at the Accident Site Nosed Over (Photo Courtesy of FAA)



Photo 2 - Substantially Damaged Vertical Stabilizer and Rudder (Photo Courtesy of FAA)



Photo 3 – Forward View of Airplane Nosed over at Accident Site (Photo Courtesy of FAA)