



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Wreckage Photo Array

ERA18TA236



Photo 1 – Runway Scars and Airplane



Photo 2 – Airplane – View from Front



Photo 3 – Airplane – View of Left Side



Photo 4 – Airplane – View of Right side



Photo 5 – Airplane – Rear Fuselage (Photo Courtesy of BCI Mass)



Photo 6 – Right Airplane Tire



Photo 7 – Propeller