



Photo 1 – Main wreckage, right wing



Photo 2 -Carburetor, fuel pouring out plug hole



Photo 3 – Carburetor, plug missing



Photo 4 – Carburetor, plug missing



Photo 5 – left-wing tip, wrinkled spar



Photo 6 – Left-wing tip, wrinkled spar