



Photo 1 –Overview of Accident Site



Photo 2 – View of Fuselage



Photo 3 – View of Propeller and Engine



Photo 4 – Closer View of Engine



Photo 5 – View of cut piece of wood.