



Photo 1 – Southwest view looking at the complete airplane wreckage at the accident site.



Photo 2 – View looking from engine compartment towards tail.



Photo 3 – View of rudder and elevators looking forward.



Photo 4 – View of propeller spinner and fractured propeller blades.



Photo 5 – View of cockpit and engine control damage.