



Photo 1 – Wreckage Path (NTSB Photo)



Photo 2 – Main Wreckage (NTSB Photo)



Photo 3 – Right Wing Section (NTSB Photo)



Photo 4 - Right Wing Section (NTSB Photo)



Photo 5 - Right Wing Section (NTSB Photo)



Photo 6 - Left Wing Section (NTSB Photo)



Photo 7 - Engine (NTSB Photo)



Photo 8 - Main Wreckage (NTSB Photo)



Photo 9 - Main Wreckage (NTSB Photo)



Photo 10 – Cockpit and Instrument Panel (NTSB Photo)



Photo 11 – Propeller Assembly (NTSB Photo)



Photo 12 - Propeller Assembly (NTSB Photo)



Photo 13 - Propeller Blade Damage (NTSB Photo)



Photo 14 – Empennage (NTSB Photo)



Photo 15 - Propeller Assembly (NTSB Photo)