



Cawley's Aviation Service

185 North Smith Road
Sky Acres Airport (44N)
LaGrangeville, NY 12540

Fax: [REDACTED]
www.cawleyaviation.com

DATE: 3/29/2019

W/O#: 19-014

MAKE: PIPER

MODEL: PA31-310

S/N: 31- 7512042

N#59984

HOBBS: 4000.1

- 1] REMOVED L/H NACELLE AUX. FUEL PUMP.
- 2] INSTALLED NEW LEFT SIDE, CUSTOMER SUPPLIED 24VT FUEL PUMP, GOLD FLOW MODEL # 480564E .
- 3] OPERATIONAL TEST PERFORMED.-NORMAL, NO LEAKS.

THOMAS P. CAWLEY
CAWLEY'S AVIATION SERVICE

AIR SERVICES, INC.
400 REGIONAL AIRPORT RD
CARROLLTON, GA. 30117
FAA Certified Repair Station Z4AR547Y

Airframe Log Book Entry
N31NW

01/29/2019
Hobbs: 17762.2

Removed RH Auxiliary Fuel Pump and installed a New Pump P/N 480564 – ops/leak check good. Serviced Nose Strut to proper specifications with dry nitrogen. I certify this Aircraft has been inspected/repared in accordance with current Federal Aviation Regulations and found it to be airworthy for return to service. Details on file under WO 6361.

Repair Station NO. Z4AR547Y
Matthew L. Martin

[Redacted Signature]

COPIES

We are starting to work on our project
Mexico and Central America campaign which
need a two hole (large back and small juts
require hyperspectral camera collection and
sensors a once. We hope this campaign
assistance for the permit paperwork through
We may also have a small project here in the
We can put two pilots and two different airplanes
once we commit to those parameters it
one early next week to st

COLLECTOR

EB

YEAR:

DATE

Date: 03/01/19
ELT inspected per FAR
Replaced elevator bun
3530.5. Replaced nose
2630.5, replacement
03/20. Inspected LH
Installed Piper kit 88
again 2957.8 or 03/2
brake discs and all
replaced. LH turn c
Ops check OK. AD
I certify that
been determined t
Frank May, A &

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				
10/25/18				Replaced nose baggage door hardware 11/16.
2423.6				AD 9-13-06 R1, inspection due 2523.6, replacement 3423.6.

Date: 11/05/18 Time: 2476.3 TT: 8915.3
Replaced all fuel cap o-rings. Replaced LH and RH brake discs and linings. Replaced LH
nacelle fuel tank transfer pump. Ops and leak check OK.
Frank May A & P [REDACTED] A
