




Photo 1 –View of helicopter during recovery (Courtesy of Department of Natural Resources)



Photo 2 – View of Helicopter After Recovery



Photo 3 – View of Instrument Panel



Photo 4 – View of Fenestron



Photo 5 – View of main rotor blades




Photo 6 – View of accessory section of engine.




Photo 7 – View of carburetor bowl.