



Photo 1 – Wreckage Path



Photo 2 – Propeller Blade Strike in Tree Along Wreckage Path



Photo 3 – Airplane Wreckage Dispersed Along Wreckage Path



Photo 4 - Airplane Wreckage Dispersed Along Wreckage Path



Photo 5 – Main Wreckage Including the Main Cabin Area and Section of Right Wing